


[2017 Chevrolet Camaro \[1G1FE1R75H0161496\]](#) | [Camaro Service Manual 10049487](#) | [Body Hardware and Trim](#) |
[Instrument Panel and Console Trim](#) | [Repair Instructions](#) | Document ID: 4180641

Multiuse Module Bracket Replacement - Instrument Panel



Multiuse Module Bracket Replacement - Instrument Panel

Callout	Component Name
1	Multiuse Module Upper Tray Bolt [4x] Caution: Refer to Fastener Caution . Tighten 2.5 N•m (22 lb in)
2	Multiuse Module Bracket Procedure 1. Disconnect the electrical connectors. 2. Transfer components as necessary.