
2017 Chevrolet Camaro [1G1FE1R75H0161496] | Camaro Service Manual 10049487 | Body Hardware and Trim | Instrument Panel and Console Trim | Repair Instructions | Document ID: 4180815

## Instrument Panel Compartment Replacement



Instrument Panel Compartment Replacement

Callout	Component Name
Preliminary Procedure Multiuse Module Bracket Replacement - Instrument Panel	
1	Instrument Panel Compartment Door Hinge [2x] <b>Procedure</b> 1. Use a suitable tool. 2. Release the retaining tabs.
2	<ul> <li>Instrument Panel Compartment</li> <li>Procedure</li> <li>1. Disconnect the instrument panel compartment door dampener from the instrument panel compartment door.</li> <li>2. Squeeze the sides of the compartment and lower the compartment past the stops.</li> </ul>